

L9	14972	motor same drive\$4 same signal\$4 same feedback\$1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 09:53
L10	791	motor same drive\$4 same signal\$4 same feedback\$1 same switch\$4 same (state or status)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 09:54
L11	11	motor same drive\$4 same signal\$4 same feedback\$1 same switch\$4 same (state or status) same resonant	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 09:54
L12	1	motor same drive\$4 same signal\$4 same feedback\$1 same switch\$4 same (state or status) same resonant	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 09:55
L13	11075	motor same drive\$4 same signal\$4 same feedback\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 09:56
L14	3138	switch\$4 same (state or status) same resonant	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 09:55
L15	123379	switch\$4 same (state or status) same control\$4 same signal\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 09:55
L16	1358	l13 and l15	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 09:55
L17	53	(resonant near20 motor) same drive\$4 same signal\$4 same feedback\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 09:56

L18	4	I15 and I17	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 09:59
L19	5	I16 and "235"/\$.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 10:03
L20	2220	(coil\$1 adj40 coil\$1) same (drive near2 signal)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 10:04
L21	9	(coil\$1 adj40 coil\$1) same (drive near2 signal) same switch same amplifier same feedback\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 10:13
L22	14	(coil\$1 adj40 coil\$1) same drive same signal same switch same amplifier same feedback\$1 same control	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 10:08
L23	18	I21 or I22	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 10:12
L24	5710	resonan\$4 near10 motor\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 10:13
L25	0	I24 and I23	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 10:13
L26	7	(winding\$1 adj40 winding\$1) same (drive near2 signal) same switch same amplifier same feedback\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 10:17
L27	1	I26 and I24	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/21 10:17